



GV-VS2800 / 2820 Integration Patch for GeoVision Software

Article ID: GV1-17-05-17-hy-1

Release Date: 05/17/2017

Applied to

Below are the compatible GV-Software applied for the patch.

Video Server (GV-VS2800 / 2820)

- GV-DVR/NVR V8.7.1.0
- GV-Control Center V3.4.0.0
- GV-Edge Recording Manager V1.2.0.0
- GV-Recording Server/Video Gateway V1.3.0.0
- GV-Redundant/Failover Server V1.1.0.0


Summary

To connect the listed GV-Software to the GV-VS2800 / 2820, install the corresponding patch file to allow the connection.




How to Install Patch Files

1. Download the patch files from the link: http://pd.geovision.tw/ira/patchfile/IPCam/IPCamera_Patch-20170310/IPCamera_Patch-20170310.zip
2. Unzip the downloaded file. Under the **IPCamera_Patch** folder, you will see the patch files.



3. Take **GV-DVR/NVR V8.7.1.0.v** for example. Double-click the **GV-DVR/NVR V8.7.1.0.v** program.
4. If the patch file is successfully installed, “**Updated successfully.**” will be displayed.



Note:

1. Make sure to download the corresponding patch file for different GV-Software.
 2. Before installing the patch file, make sure the software you are using is updated according to the version numbers listed above.
-