

[FAQ]

Why is part of the 5 MP fisheye view missing?

Article ID: GV12-11-29-t

Release Date: 11/29/2012

Applied to

5 MP GeoVision Fisheye IP Camera


Question

Why is part of the 5 MP fisheye camera view missing?



Answer

This is a hardware specification of the 5 MP fisheye cameras. The circular lens of the fisheye camera is slightly larger than the size of the camera sensor. The missing areas of the fisheye view are where the lens size exceeds the sensor size.



You can eliminate the dark areas of the camera view by reducing the size of the Image Alignment circle, but field of view will also be reduced. To adjust the image alignment, follow the steps below:

1. Login to the Web interface of the fisheye camera, right-click the live view and select **Geo Fisheye**.
2. Right-click the live view again, select **Fisheye Option** and select **Image Alignment**.
3. Drag the red circle to adjust the image alignment.

